# **THUNDERBOLT**

## **INDUSTRIAL STRENGTH SPRAY & WIPE DEGREASER**



Ready-to-use, high-performance cleaner and degreaser provides quick and easy removal of permanent ink marks, grease and grime from hard, non-porous surfaces.

### **Directions**

- Apply directly to surface while holding 6-12 inches from surface.
- For vertical surfaces, start at bottom and work upwards.
- Wipe away soil with paper towel, cloth or damp sponge.



For Use On The Toughest Of Soils

#### **Specs**

Dilution: RTU pH Level: 11.0-12.5 Color: Green Fragrance: Spearmint Pack Types: Quart

- RTU Spray and Wipe
- Cuts Through Heavy-Duty Grease
- Removes Ink Marks From Non-Porous Surfaces
- Residue-Free

#### **Recommended For**

- Floors and Walls
- Countertops
- Tile and Grout
- Wood
- Stainless Steel
- Desk and Workstations

**Features**